

FELLER HOLDING CORPORATION  
1051 North 1100 West  
St. George, Utah 84770

March 29, 1995

Mr. Lary Gore, Geologist  
U. S. Bureau of Land Management  
Dixie Resource Area  
345 East Riverside Drive  
ST. George, Utah 84770

Subject: Additional Information Requested in Letter of  
March 14, 1995, 3809, UTU - 73395, (UT-045)  
NOTICE OF OPERATION -Pursuant to CFR Title 43  
Paragraph 3809.1-3, Notice-disturbance of 5  
acres or less.

Dear Mr. Gore:

This letter and appended maps and photographs are hereby transmitted to provide the information requested in your March 14th letter. Material included is as follows:

1. Copies of a portion of the Veyo Quadrangle Orthophoto Map illustrating the disturbances that existed prior to the 1976 date of the photographs used to make the orthophoto.
2. Twenty photographs of some of the existing disturbance. These photographs were taken to document the existing disturbances. Location of the photographs is illustrated on Page 3 of the appended maps and photographs.
3. As mining will be conducted along the existing roads and exposed faces of gypsum, very minor overburden or soil removal is anticipated. When it becomes necessary to stockpile overburden or soil, sites will be selected on previously disturbed areas where possible.
4. Paragraph 4 of your letter states in part:  
"You need to specify what you consider the minimal width for roads to be."  
The existing roads are eight feet to over seventeen feet wide and average circa twelve to fourteen feet wide. Though some grading and removal of rocks may be required, it does not appear that additional road widths will be needed.

Page 2 Feller Holding to Mr. Gore

5. The projected start-up date will be as soon as our schedule will permit after April 14, 1995. It is not anticipated that equipment will be stored at the site during periods of non-operation.


The operator as stated in our NOTICE will be Feller Stone Inc., telephone number - 801673-2349.

Sincerely,


A handwritten signature in dark ink, appearing to read "Russell C. Feller", written over a horizontal line.

Russell C. Feller  
President, Feller Holding Corporation





1 MILE  
100 FEET  
METER




Page 53  
Location of Photographs

VEYO, UTAH  
N3715-W11337.5/7.5


1976

ADVANCE PRINT





Existing Roads & Disturbance  
Roads 8' to 17' Wide  
Average 12' to 14' Wide




QUADRANGLE LOCATION

VEYO, UTAH  
N3715-W11337.5/7.5

1976

ADVANCE PRINT





17' 30"

4130

4129

4128

4127

4126000m N

40'

264


265

266000m E

37° 15' 113° 37' 30"

LE

*Uncolored Copy*



QUADRANGLE LOCATION

VEYO, UTAH  
N3715-W11337.5/7.5

1976

ADVANCE PRINT

*Page 4A*





Gypsum outcrop on northern portion of the  
TJKSJ Placer Mining Claim.

Addendum to NOTICE of Operations to the  
Bureau of Land Management

Feller Holding Corporation

TJKSJ Placer Mining Claims  
in Sections 27 & 28, T.40 S., R.16 W.

Site disturbance prior to the location of the  
TJKSJ Placer Mining Claims. Prospect roads  
and mining operations conducted prior to the  
year 1976 as evidenced by the enclosed  
portion of the seven and one-half minute  
Veyo Orthophoto Quadrangle. The photograph  
locations are marked on Page 3, and on Page 4  
the location of existing roads have been  
traced in red.





Looking easterly from Utah 18 Highway at the northern portion of the TJKS #1 placer claim. Gypsum outcrop in right center of photo above road.



Looking east south east at gypsum outcrop and existing road on the north end of TJKS #1 claim.





Looking south easterly at the central portion of the TJKSJ #1 placer claim. Gypsum outcrops & existing roads.




View farther south east of the top photograph.






Looking northerly along the section line between Sections 27 & 28, T.40 S., R.16 W. Note entrance road near center of photo. View is from SW corner Sec. 27, SE Cor. Sec. 28.



View of entrance road turn-off and right-of-way fence Utah Highway 18.





View of gravel pit located in SE  $\frac{1}{4}$  of Sec. 28,  
on the NW side of entrance road.



Existing road to gypsum outcrops on TJKSJ  
#s 1 and 3. Right-hand fork in the lower right  
goes to the TJKSJ and TJKSJ #2 area





View of existing roads northwesterly of photos  
on page 9



View of road on TJKSJ #2 is in the edge of  
the gypsum outcrop





Roads and cut exposing gypsum in southern portion of TJKSJ placer claim.



Roads running northwesterly on the TJKSJ #1 claim






*Access road to TJKSJ #2 area*



*Roads in southeastern portion of TJKSJ placer claim. View is looking easterly.*





View of lower access road looking northwesterly.  
Photo taken near central portion of TJKSJ #1 claim.




Upper access road on TJKSJ placer claim. View  
is looking north westerly. Note some rocks eroded  
from cut blocking portions of road that will be  
moved to allow safe use of existing road.





View of access road & gypsum outcrop. Looking westerly across north central portion of TJKSJ #1



Road and gypsum exposed along roadway. In northern portion of TJKSJ #1.








Gypsum outcrop on right of road. View looking northerly in northern portion of TJKS #1 claim.



Looking southerly from point 200 feet northerly from top photo.





- ROAD CLASSIFICATION**
- |                                    |  |
|------------------------------------|--|
| Primary highway,<br>hard surface   | Light-duty road, hard or<br>improved surface |
| Secondary highway,<br>hard surface | Unimproved road                              |
- Interstate Route    ○ U. S. Route    ○ State Route

VEJO, UTAH  
N3715-W11337.5/7.5

(ST. GEORGE  
3258 II